

AE (LT71141 – ZF 5 Speed)
 Alfa Romeo (all vehicles)
 Aisin Warner AW-1, JWS 3309, JWS 3324, M315 A-1, T IV
 Allison C-3, C-4
 Allison TES 295
 Allison TES 389
 American Motors ATF +3 (SM7176-E, ATF+4 (MS9602)
 AS 68 RC (T IV)
 ATF Type A Suffix A
 Audi/VW G 052 025-A2
 Audi/VW G-052-162-A1
 Audi 5 HP LT 71141 (ZF 5 HP 18 FL, 19FL, 24A)
 Audi 5 HP LT 71141 (G-052-162-A1, A2)
 Audi 5 HP (ZF 5 HP 30)
 Audi G-055-025-A2 (JWS 3309)
 BMW ETL-7045, 7045E (83 22 0 026 922)
 BMW 7045E (3 series)
 BMW LA2634
 BMW 5 HP LT 71141 (ZF 5 HP 18 FL, 19FL, 24A)
 BMW 5 HP LT 71141 (83 22 9 407 807)
 BMW 5 HP (ZF 5 HP 30)
 BMW ETL-8072B (83 22 0 024 359)
 BMW MINI 83 22 0 402 413 9 (JWS 3309)
 BMW 5 Series (Texaco ETL-8072B)
 Caterpillar Power Shift TO-2
 Chrysler ATF +3 (MS 7176-E)/+4 (MS 9602)
 Chrysler Dodge MOPAR AS 68 RC (T IV)
 Daimler NAG-1
 Deawoo LT 71141
 Esso LT 71141
 Fiat (All vehicles), TYPE T IV
 Ford MERCON® (XT-2-QDR, XT-2-QSM SYN)
 Ford MERCON® V
 Ford MERCON® LV
 Ford MERCON® SP
 Ford WSS M2C 922 A1, 924-A (XT-8-QAW) (JWS 3309)
 GM DEXRON® II, IID, IIE, III, IIIG, IIH
 GM DEXRON® VI
 GM T IV
 GM Type A
 Honda/Acura ATF Z1, DW-1, Premium
 Honda Z-1
 Hyundai NWS-9638, SP-II, SP-III, SP-IV
 Isuzu Besco ATF II, ATF III
 Jaguar ATF 3403 M115, LT 71141, jlm 20238
 JASO 1-A
 JASO 2A-02
 JATCO FWD in Nissan, Rover 800, VW Polo (Texaco N402)
 JATCO – Jaguar X Type 2001-2005 (Idemitsu K-17)
 JATCO 3100 PL085
 JEEP ATF+3, ATF+4
 JWS 3309 (Aisin Warner)
 JWS 3309 (T-IV)
 JWS 3324 (WS)
 Kia ATF Red 1, SP-II, SP-III, SP-IV
 MAN 339F, V1, V2, Z1, Z2, Z3
 Mazda ATF-M III
 Mazda ATF – MV
 Mercedes Benz 223.1, 236.1, 236.2, 236.5, 236.6, 236.7, 236.9, 236.10, 236.12, 236.41
 MB ZF 4 HP20
 MB 5 Speed 1996-2006 (Shell 3403)
 Mini Cooper 83 22 0 402 413 9 (JWS 3309, T IV)
 Mitsubishi Diamond SP-II, SP-III, SP-IV, Dia
 Nissan/Infinity Matic D/J/K/S
 NAG 1 (Jeep Cherokee), NAG 2 (Chrysler)
 Opel (All vehicles)
 Peugeot ZF 4 HP20
 Porsche ATF 3403-M115, LT 71141, T IV (JWS 3309)
 Queen J2
 SAAB T IV (JWS 3309)
 Saturn T IV (JWS 3309)
 Scion (all vehicles)
 Shell M 115
 SP-II
 SP-III
 Subaru ATF, ATF HP
 Suzuki ATF 3309
 Texaco ETL-7045E
 Texaco ETL-8072B
 Toyota T-II/T-IV
 Toyota WS
 Voith G607 G13636 (55.6336.XX)
 Voith Turbo H55.6335.3X
 Volvo 97340, 97341, T IV (JWS 3309)
 VW 5 HP LT 71141 (ZF 5 HP 18FL, 19FL, 24A)
 VW 5 HP LT 71141 (VW G-052-162-A1, A2)
 VW G-052-182-A2
 VW 5 HP (ZF 5 HP 30)
 VW TL 521 62
 VW TL52162
 ZF 3 and 4 speed transmissions
 ZF TE ML 02F, 03D, 04D, 05L, 14A, 14B, 14C, 16L, 17C
 ZF TE-ML-09
 ZF TE-ML 11A and 11B

CONTACT

BIMROSE Lubricants,

P.O. Box 5435,
 15 Pinacle Street,
 Brendale, Qld. 4500.

Telephone: 07) 3881 1733
 Fax: 07) 3881 1708
 Email: admin@prolube.com.au
 Internet: www.bimrose.com.au

Issue Date 12/12/2013